Idaho PUC Pipeline Safety Inspection Summary

Inspector(s):	Russe	0	Date(s):	5-Sep-19
Company/Owner:	Intermountain Gas Company		Unit/OPID:	8160
Lange stien Town (2 Time /1 day)				
Inspection Type & Time (1	day)	Tota	l Inspection Days:	1
Standard: Construction:	1 Training:	(T)(D) Integrity Manageme	nt: Incident:	
M/M: Follow-up:	OQ:	Damage Prevention:	D&A:	
Inspection Summary				
A construction inspection was performed on Das-co, a contractor for Intermountain Gas Company.				
5 Sept 2019: (1.0 Construction) Observed a Dasco crew excavating for a new service. They were exposing the stub and riser location but decided to come back with the right equipment at a later date due to a concrete driveway being poured before the gas was installed. Typed up report Areas observed during this project were: Excavating, Line locating				
Attachments: IPUC Form 4 Construction Ins		C,		
Das-co Daily Itineraries located in file for the project.				
OQ's for all observed employees are located in file for the project.				
Corrective Action Required:		ow-up Required:	Yes No	Х
Yes No	Х		by (date):	
Inspector (Lead):			Date:	1.1.1.
Kyle Russo		7	Data	10/1/19
Reviewer:	1. mand the	Hr_	Date:	A-16 2019